GEIST™ TEMPERATURE, AIRFLOW, HUMIDITY AND DEW POINT SENSOR

Quick Installation Guide

Part Number:

RTAFHD3

Description

The RTAFHD3 is a temperature, airflow, humidity and dew point sensor.

NOTE: *This sensor can span a total cable distance up to 600 ft from the Geist environmental monitoring device.*

NOTE: *The sensor must be mounted perpendicular to the airflow for effective measurement.*

Installation

1. Mount the sensor anywhere in the data center with zip ties or Velcro tape.
2. Plug the uplink cable into sensor port (RJ12/) of the Geist environmental monitoring device or rack PDU.

Once connected, the Geist environmental monitoring device automatically detects and identifies the sensor.

Geist™ Temperature, Airflow, Humidity and Dew Point Sensor

Temperature Accuracy Charts





To contact Vertiv Technical Support: visit www.VertivCo.com

© 2019 Vertiv Co. All rights reserved. Vertiv and the Vertiv logo are trademarks or registered trademarks of Vertiv Co. All other names and logos referred to are trade names, trademarks or registered trademarks of their respective owners. While every precaution has been taken to ensure accuracy and completeness herein, Vertiv Co. assumes no responsibility, and disclaims all liability, for damages resulting from use of this information or for any errors or omissions. Specifications are subject to change without notice.